## Work Order ID 53347

November 2, 2009 10:40:59 AM



Page 1

D2891-1 Item ID: Accept Setup Start **Revision ID: A**1 Stop 2.25 Support Item Name: **Start Qty: 12.00 Start Date:** 02/11/2009 **Cust Item ID: Required Date:** 13/11/2009 Req'd Qty: 12.00 **Customer:** Reference: Run Start Date: 9-1/-2 Tooling: Process Plan: **Approvals:** Date: Stop Date: \_\_\_\_\_ QC: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Draw Draw Plan Accept Reject Reject Insp. **Work Center ID Description** Number Rev. Code **Qty** Qty Number Stamp **Run Hours Draw Nbr Revision Nbr** D2891 Rev A1 100 0.00 HAAS CNC VERTICAL MACHINING #1 ant 09/1/04/JL 09/11/65 0.00 HAAS 1 Memo , HAAS CNC vertical machine #1 Machine as per Folio FA046 □ Tumble & Deburr 110 QC2- Inspect parts off machine FAI/FAIB 0.00 2/1/04/JL 2/1/05 2/1/05 0.00 Memo Quality Control 120 QC8- Inspect parts - second check 0.00

QC

**Quality Control** 

Memo

0.00

3

## Work Order ID 53347

**A**1

Page 2

November 2, 2009 10:40:59 AM

**Required Date: 13/11/2009** 

Item ID:

D2891-1

Accept



Setup Start



Stop

**Revision ID:** Item Name:

2.25 Support

QC:

02/11/2009

**Start Qty: 12.00** Req'd Qty: 12.00

**Cust Item ID: Customer:** 

Draw

Number

Reference:

**Start Date:** 

**Approvals:** 

Process Plan:

Date:

**Tooling:** 

Date:

Run

Accept

**Qty** 

Start

Reject

Date:\_\_\_\_\_

**SPC (Y/N):** 

Set Up/

**Run Hours** 

Date:\_\_

Draw

Rev.

Plan

Code

Stop

Reject

09

**Qty** 

Number Stamp

Insp.

Sequence ID/ Work Center ID

125

135

SprayPaint

**Spray Painting** 

Operation Description

Spray Painting per QSI005 4.2

0.00

0.00

Prime BJJOA 18
Spray Painat Delfleet Blue B 113171
Clear Delfleet B 113 088

Memo

QC14- Inspect Spray Paint

Memo

0.00

0.00

BT 69,11-25

**Quality Control** 

150

Packaging

Packaging

Identify as per dwg & Stock Location: X + UseS

0.00

Memo

0.00

## Work Order ID 53347

Page 3

November 2, 2009 10:40:59 AM

Item ID:

D2891-1

**Revision ID: A**1

2.25 Support **Item Name:** 

**Required Date: 13/11/2009** 

**Start Date:** 

02/11/2009

**Start Qty: 12.00** 

Req'd Qty: 12.00



Accept

Setup

Run

Start

Stop



**Cust Item ID:** 

**Customer:** 

Reference:

**Approvals:** 

Process Plan: \_\_\_\_\_

**Operation** 

**Description** 

Date:

Date:

**Tooling:** 

**SPC** (Y/N):

Set Up/

Date:

Date:

Start



Stop

Sequence ID/ Work Center ID

QC21- Final Inspection - Work Order Release

0.00

Run Hours

Draw Number

Plan Draw Rev. Code

Accept Qty

Reject Reject Qty

Insp. Number Stamp

160

QC

Quality Control

Memo

0.00

- 09/11/25 X Pl0911-25

## **Picklist Print**

November 2, 2009 10:41:04 AM

Work Order ID: 53347

D2891-1RevA1 **Parent Item:** 

Parent Item Name: 2.25 Support

**Comments:** 



Start Date: 02/11/2009

**Required Date:** 13/11/2009

**Start Qty: 12.00** 

Required Qty: 12.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
DSK076RevA		Manufactured	No			110	Each	10.0000	6.0000			

D2891-1 TURNING DETAIL

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
MAT	10		
42244	1		
43384	4		
51184	5		·
N366	<b>,~</b>		6 Mark
•		og/14/05	0 00000

DART AEROSPACE LTD	Work Order:	5332/1
Description: Ø2.250 Support	Part Number:	D2891-1
Inspection Dwg: D2891 Rev: A1		Page 1 of 1

		FIRST A	ARTICLE INS	SPECTION	DIMENSIO	ON SHEET	Γ	
			X First A	rticle [	Proto	type		
					<sup>'</sup> Record	Actual Dime	ensions	
Dim	Min	Max	Go/No Go Gauge	1	2	3	4	5
			, <u></u>	HAAS Section	n			
AA	0.188	0.193		.190	191	.191	191	.189
AB	0.240	0.260		1920	.357	250	9066°	-249
AC	0.115	0.150		125	.135	7513	.125	.126
AD.	0.040	0.060		1049	720	2050	048	.050
AE	0.010	0.020	<u> </u>	010	010	0/0	1016	-010
AF	0.240	0.260		R. 250	B,250	A 350		250
AG	0.290	0.310		P06.	, 310	BP6.	.306	-310
AH	0.115	0.150		139	2/38	.\37	·\38	-137
ΑĪ	0.454	0.474		465	.465	.465	. 465	.465
AJ	2.779	2.789		2783	3.782	3.783	2.783	2.784
AK	0.240	0.260		R. 250	2.250	D 350	2006.8	250
AL	1.002	1.042		1.037	1,042	1.037	1.040	1.035
AM	0.053	0.073		Q.063	R. diz	B.003	8.003	-063
AN	0.257	0.262		. 928	826	358	876.	-25+
AO	1.663	1.683		1.674	1.674	1.075	1.674	1.673
AP	0.053	0.073		6.003	CV2, 20	1.013	8.063	063
AQ	0.022	0.042		Q.032	R. 032	B. 033	8.032	.032
AR								
AS								
AT								
			Accept/Reject		,			<u> </u>
	Measure	d by: mv-	/JL			Date:	09/11/6	35
	Audite	d by:   \$ =				Date:	09/11/06	
Proto	type Appr	oval:				Date:		
Rev	Date	Change						Approved
Α	02.12.12	New Issue					/RF 1,A	21
В	08.04.21	Reformat				KJ	/JLM A	\J]

DART AEROSPACE LTD	Work Order:	
Description: Ø2.250 Support	Part Number:	D2891-1
Inspection Dwg: D2891 Rev: A1		Page 1 of 1

		FIRST	ARTICLE INS	SPECTION	DIMENSIO	ON SHEET	Г			
			X First A	rticle [	Proto	type				
Record Actual Dimensions										
Dim	Min	Max	Go/No Go Gauge	46	727	84	<b>¥</b> 9	\$10		
	<u> </u>		ı	IAAS Section	n					
AA	0.188	0.193		1-189	189	1-189	1-189	-189		
AB	0.240	0.260		.250	251	.250	250	-249		
AC	0.115	0.150		126	.125	.125	-125	.126		
AD	0.040	0.060		.049	-050	-050	.050	049		
AE	0.010	0.020		010	.010	-010	-010	-010		
AF	0.240	0.260		-850	,250	-250	-250	.250		
AG	0.290	0.310		.310	-310	.310	.310	-310		
AH	0.115	0.150		1)37	.137	-137	-137	-137		
AI	0.454	0.474		-465	.465	-465	-H64	464		
AJ	2.779	2.789		2.784	2.784	73.784	2.784	2.784		
AK	0.240	0.260		- 250	-250	.250	250	-250		
AL	1.002	1.042		1.035	1.033	1.038	1.040	1.037		
AM	0.053	0.073		~063	-063	. රුයි	-063	-063		
AN	0.257	0.262		.257	-257	-257	-257	.257		
AO	1.663	1.683		1.674	1.675	1.673	1.672	1.672		
AP	0.053	0.073		-063	-063	-063	-063	-063		
AQ	0.022	0.042		132	-032	.032	.032	.032		
AR										
AS										
AT								<u> </u>		
			Accept/Reject							
	Measure	d by:	<u>()</u>			Date:	Oglilo			
l						1				
	Audite	d by:	15			Date:	09/11/08			
Proto	type Appr	oval:				Date:				
Rev	Date	Change				Re	vised by	Approved		
A	02.12.12	New Issue					/RF 1.0	- 1		
B	08.04.21	Reformat					JIM A	all		
	100.04.21	Reformat			<del></del>		····	<del>/~</del> _		

DART AEROSPACE LTD	Work Order:	
Description: Ø2.250 Support	Part Number:	D2891-1
Inspection Dwg: D2891 Rev: A1		Page 1 of 1

			X First A	Article	Protot	ype		
					Record	Actual D	mensions	
Dim	Min	Max	Go/No Go Gauge	11	12	3	4	5
				HAAS Section				
AA	0.188	0.193		1189	-189			
AB	0.240	0.260		250	249			
AC	0.115	0.150		-125	125			
AD	0.040	0.060		.050	.050			
AE	0.010	0.020		-010	.010			
AF	0.240	0.260		250	-250			<b>_</b>
AG	0.290	0.310		-310	310			
AH	0.115	0.150		-137	137			
ΑI	0.454	0.474		· H70	769			
ΑJ	2.779	2.789		2784	2.784			
AK	0.240	0.260		- 250	.250			
AL	1.002	1.042		1,038	1.031			
AM	0.053	0.073		.063	.063			
AN	0.257	0.262		.257	.257			
AO	1.663	1.683		1.674	1.674			
AP	0.053	0.073		-063	-063			
AQ	0.022	0.042		٠٥٤٦	-03a			_
AR								
AS								
AT	i		<u> </u>	<b>_</b>				
			Accept/Reject					
	Measured	by: )				Dat	e: 09/11/0	5
			/					
•	Audited	by: Sv	3			Dat	e:   09/11/01	<u> </u>
Proto	type Appro	val:				Dat	e:	
Rev	Date	Change					Revised by	Approve
Α	02.12.12	New Issue					KJ/RF	1
<del></del>	00.04.04						KI/IIM OKL	

В

08.04.21 Reformat

